



Assembly Instructions

1) Slide the ferrule onto the cable. Strip the cable to the dimensions shown. Take care not to nick the centre conductor or braid.


A = 9mm
B = 4mm
C = 3mm



2) Crimp the contact onto the centre conductor.



3) Insert the contact into the body until it butts against the inner body. Make sure the braid is on the outside of the mandrel. Slide the ferrule over the braid until the ferrule butts up against the body. Crimp the ferrule using the correct tool for the connector.



CAD Issue	SN	2	03 Aug 01
First Issue	DJH	1	07 Nov 00
DESCRIPTION OF REVISION	APPVD	ISS	DATE



Cinch Connectivity Solutions, Ltd
11 Bilton Road
Chelmsford
Essex CM1 2UP, England
T: +44 (0) 1245 342060
F: +44 124 535 8938

SCALE: Not To Scale

DIMENSIONS: mm

TOLERANCES:

DRAWN BY:

S Nash

CHECKED BY:

M Nielsen

APPROVED BY:

P Couzens

DATE:

29 Aug 01

DESCRIPTION:

Stripping and Assembly
Instructions for FME Crimp
Plug

DRAWING NUMBER:

VAIR1101

PAGE: 1 OF 1