- Fixed mounting brackets with 2 M2.5 screws to Ice Tower Cooler. Please pay attention to the direction of mounting brackets.

- Add copper stick and nuts to mounting brackets.

- Paste thermal tape to Raspberry Pi's CPU SOC.

- Fixed mounting brackets to Raspberry Pi with copper sticks.

- Fixed Acrylic protection panel to Raspberry Pi with M2.5 screws.

- Connect the red wire to 5V and black wire to GND on Raspberry Pi's GPIO.

- Connect power supply to Raspberry Pi and Have fun!