

SOLDERING STATIONS

| MODEL | IRON | ELEMENT |
|------------|------|---------|
| 469 | B022 | C011 |
| 937+ PRO* | B030 | PCX-01 |
| 9378 PRO** | B028 | PCX-01 |

** Multi-tool compatibility. (See product listing)

TWEEZER STATIONS

| MODEL | TOOL | ELEMENT |
|-------|------|---------|
| 950 | B004 | C001 |
| | T001 | C002 |
| 702A+ | B016 | C012 |
| | T007 | C002 |

For models with an asterisk (*) visit our website to find appropriate tweezers. (Sold Separately)

DE-SOLDERING STATIONS

| MODEL | IRON | ELEMENT | GUN | ELEMENT |
|---------|-------|---------|--------|---------|
| 474A++ | N/A | N/A | B1002A | C005A |
| 701A++* | B003A | C009 | B1002A | C005A |
| 8800 | N/A | N/A | SELF | C088 |

SCAN HERE



To view all spare parts
for your station

HOT AIR REWORK STATIONS

| MODEL | IRON | ELEMENT | HEAT TUBE | ELEMENT |
|---------|-------|---------|-----------|---------|
| 888A | B016 | C012 | AO20982 | AO20094 |
| 899A++ | B004 | C001 | AO20972 | AO10096 |
| 968A+* | B003A | C009 | AO20962 | AO20094 |
| 852A++ | N/A | N/A | AO20962 | AO20094 |
| 8032A++ | N/A | N/A | AO20972 | AO10096 |

Please note: Hot air gun elements are sold in 110V and 220V versions

ALL-IN-ONE STATIONS

| MODEL | IRON | ELEMENT | HEAT TUBE | ELEMENT | TOOL | ELEMENT |
|---------|------|------------|-----------|---------|--------|---------|
| 866* | B016 | C012 | AO20982 | AO20094 | N/A | N/A |
| 738H | B018 | C031 | AO20962 | AO20094 | T005 | C002 |
| 2702A+* | B012 | WQ/LF-Tips | AO20962 | AO20094 | B1003A | C006A+ |
| 2703A+* | B012 | WQ/LF-Tips | AO20962 | AO20094 | B1003A | C006A+ |



For technical info and help please visit
our new SRA Resource Center.

There you'll be able to find product overviews,
repair guides, maintenance tips, and more!

www.blog.sra-solder.com

| KEY: |
|----------------|
| STATION |
| SOLDERING IRON |
| HOT AIR GUN |
| DESOLDER GUN |
| TWEEZERS |